



## TOYOTA & LEXUS

## RECALL DATE: 04/09/2024

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Toyota Crown, BZ4X	Ocober 29,2021 through April 2, 2024	116
Lexus NX350	March 31,2021 through April 6,2023	101

\*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

## Recall consequence

The subject vehicles are equipped with a Toyota Safety Sense (TSS) 3.0 system or Lexus Safety System Plus (LSS +) 3.0, containing a forward recognition camera to detect objects for certain driver assistance features, including the Pre-Collision System (PCS). Due to the programming of the front view camera software, the memory inside the front view camera fails during processing when the ignition is turned off. If this occurs, The pre-collision system will not be activated on the next ignition start, causing warning lights to illuminate, audible chimes to sound, and messages to display on the instrument panel.

Recall Action

To reprogram the Forward Recognition Camera

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.go





