



Recall Date: 4/11/2024

| Brand of Commodity | Year of Production | Number of Affected Commodities |
|--------------------|--------------------|--------------------------------|
| SUZUKI JIMNY       | 2018-2019          | 38                             |

#### Recall consequence

In these vehicles, Due to the deformation and swelling of the fuel feed impeller in the fuel pump made of resin, the fuel injection quantity is incorrect, the material leaks into the fuel container, and in the worst case, the engine stops while driving.

#### Recall Action

Due to the importance of customer safety to the agent, as a precautionary measure, The agent will replace the fuel pump. ensuring the safety, and reliability of the Vehicle

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>