



Recall Date: 17/11/2024

## Accord-city-odyssey-crvcivic 2018-2019

Brand of Commodity	Year of Production	Number of Affected Commodities	
Accord-city-odyssey- crv-civic	<b>2018</b> -2019	Total: 1814 units	

Recall consequence

Material of plastic impeller from some lots used inside fuel pump have low density, and some had many cracks at the process of drying fuel for inspection. This resulted in impeller swelling and deformation due to immersion in fuel and temperature on market, causing less clearance between impeller & pump cover and this will cause the fuel pump to lock resulting in engine stalling or engine not starting

**Recall Action** 

The procedure will be carried out according to the technical instructions received from Honda.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.gov.om





