

Recall

KIA

RECALL DATE: 05-02-2025

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Soul (AM)	2010-2013	20
Sportage (SL)	2010-2013	1911
Cadenza (VG)	2009-2016	232
Carens (RP)	2012-2018	16
Quoris (KH)	2012-2017	39

^{*}Not all vehicles in this production period, are affected.

Recall consequence

On some Soul (AM) - 2010-2013, Sportage (SL) - 2010-2013, Cadenza (VG) - 2009-2016, Carens (RP) - 2012-2018, Quoris (KH) - 2012-2017 produced within specific production date range, The HECU (ABS) unit in the engine room may experience an internal electrical short circuit due to overcurrent fuse and thereby increasing the possibilities of an engine compartment fire while the vehicle is driven or while parked. Illumination of MIL or ABS lamp may happen and burning/melting smell from the engine compartment may occur. The estimated defect ratio is 1%. However, Kia is conducting this recall as preventive measure to avoid the risk.

Recall Action

Verify affected vehicles as per the VIN list, Replace HECU (ABS) unit fuse kit as per KMC recommendation. All affected vehicles will be inspected and repaired at no expense to the vehicle owner.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.gov.om







[#]Subject to revision, based on the information received from the manufacturer, from time to time.