

Recall Date : 25/02/2025



Brand of Commodity	Year of Production	Number of Affected Commodities
Nissan Pathfinder	2022 - 2023	2
INFINITI QX60	2022 - 2023	5

Recall Cause

There is a supplier welding quality concern wherein the rear inboard seat bracket weld may detach from the driver's seat frame rail. Should this happen, in the event of a road traffic accident, the seat and the seat belt anchor may separate from the seat rail, possibly causing the position of the driver to change in relation to the airbag, potentially increasing the risk of injury.

Recall Cause

Inspect the rear inboard driver seat rail-to-frame weld and replace the driver seat cushion frame if needed.

To check the serial numbers of the affected commodities, please visit the website for recalls and warnings: <http://recall.pacp.gov.com>



خط المستهلك
Consumer line
80079009
80077997



الحشار للسيارات
Al Hashar Automotive

INFINITI

Call Us Toll-Free at
800 88188

NISSAN

Call Us Toll-Free at
800 88088