



## 2025 (DT) RAM 1500 Pickup

Recall Date: **20 May 2025**

Brand of Commodity	Year of Production	Number of Affected Commodities
2025 (DT) RAM 1500 Pickup	2025	16

### Recall consequence

The front wheel bearing on about 900 of the above vehicles may have been built with damaged encoder rings causing a loss of wheel speed signal (WSS) which may disable Electronic Stability Control (ESC). Failure of the ESC system can, in certain driving conditions, cause a vehicle crash without prior warning.

### Recall Action

Road Test, Inspect, and Replace Both Front bearings / Hub Assemblies (If Required ).



To check the serial number of the affected items, please visit the Recalls and Warnings website by scanning the QR code.



For more information  
**800 22 008**  
[www.mhdacere.com](http://www.mhdacere.com)



[www.cpa.gov.om](http://www.cpa.gov.om)

Consumer Protection Authority  
80079009 • 80077997 خط الاستهلاك