



RECALL

RECALL DATE: 17-SEP-2025

GEELY EMGRAND

BRAND OF COMMODITY	YEAR OF PRODUCTION	NUMBER OF AFFECTED COMMODITIES
GEELY EMGRAND	2023-2025	869

RECALL CONSEQUENCES

Fuel filler cap may create vacuum pressure within the fuel system after extended operation. And in extreme cases, this pressure differential could potentially deform the fuel tank and create contact with the fuel pump plunger, posing a leakage hazard.

RECALL ACTION

Inspect and Replace Fuel Tank Cap, if any leakage noticed on fuel tank system, affected parts needs to be replaced accordingly.

TO CHECK THE SERIAL NUMBERS OF THE AFFECTED COMMODITIES, PLEASE VISIT THE WEBSITE FOR RECALLS AND WARNINGS: [HTTP://RECALL.PACP.GOV.OM](http://RECALL.PACP.GOV.OM)



وللتحقق من الرقم التسلسلي للسيارة
المتأثرة يرجى زيارة مواقع الاستدعاءات
والتحديثات عن طريق مسح رمز الاستجابة



مركز تاول للسيارات ش.م.م
Towell Auto Centre LLC



24229100



www.cpa.gov.om

Consumer Protection Authority
خط المستهلك 80079009 - 80077997

التاريخ : فبراير 2025

الاصدار : 04

الرمز: SOP-093-02