



Recall

HINO 300 SERIES

RECALL DATE: 16.11.2025

Brand of Commodity	Year of Production*	#Number of Affected Commodities
HINO 300 Series [EuroIII] XZU710L-WKMQKV3 4.0L Chassis Cab 4x2 2 Doors:	Sep 12th 2023 to Jan 7th 2025	40
HINO 300 Series [EuroIII] XZU720L-WKFTLV3 4.0L Chassis Cab 4x2 2 Doors:	Sep 12th 2023 to Jan 7th 2025	10
HINO 300 Series [EuroIII] XZU720L-WKMQKV3 4.0L Chassis Cab 4x2 2 Doors	Sep 12th 2023 to Jan 7th 2025	14
HINO 300 Series [EuroIII] XZU720L-ZKMQKV3 4.0L Chassis Cab 4x2 4 Doors	Sep 12th 2023 to Jan 7th 2025	645

*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

On 300 Series due to inappropriate method of bolt tightening during installing the carrier bracket of spare tyre hanged on the rear overhand, the tightening torque may not be adequate. Therefore if the vehicle continues to operate in such condition, the bolts may loosen by vibration of the vehicle's operation and in the worst case, it may cause a fall of the spare tyre with the carrier bracket.

Recall Action

Retighten the spare tyre carrier bracket tightening bolts with specified torque if the bracket is fitted properly. If any of the tightening bolts are already loosened, replace the spare tyre carrier bracket, bolts and nuts as per Hino Motors prescribed work procedure.



To check the serial number of the affected items, please visit the Recalls and Warnings website by scanning the QR code.



Contact details: Toll free - 80073000
Working days: Sunday - Thursday
Working Time: 8:00 - 17:00 hrs.



www.cpa.gov.om

Consumer Protection Authority
80079009 - 80077997 خط المستهلك