

Recall

Commodity,s Picture

Recall Date: 29/12/2025

Commodity,s

Brand & Model



HYUNDAI KONA SX2

Brand of Commodity	Year of Production	Number of Affected Commodities
Hyundai KONA	2024	17

Recall consequence

The exhaust gas recirculation (EGR) valve assembly in the subject vehicles may contain a sensor that was contaminated with solder flux during supplier manufacturing, which could potentially result in an electrical short. An electrical short within the EGR valve could lead to a malfunction of the EGR valve or crank position sensor, both of which reside on the same power circuit, resulting in MIL illumination and/or a sudden loss of power while driving.

Recall Action

Dealers will inspect and, if necessary, remove and replace the finish on rear seat lower child seat LATCH anchorage bars,



To verify the serial number of the goods Those affected please visit the recalls website And warnings by scanning the response code



80050002



www.cpa.gov.om

Consumer Protection Authority
80079009 - 80077997 خط المستهلك