

# Recall

## AFRICA TWIN

RECALL DATE: 08.02.2026



Brand of Commodity	Year Of Production	Number of Affected Commodities	
		Honda	Africa Twin
Africa Twin	2020	7	
	2021	23	
	2023	27	
	2024	5	
	2025	19	

### Recall consequence

The horn does not sound, or the headlight may not be switched from low beam to high beam.

### Recall Action

Eliminate the joints inside the handlebar switch wire harness and replace the handlebar switch housings with countermeasure parts.



To verify the serial number of the goods Those affected please visit the recall website And warnings by scanning the response code

2025 Africa Twin



[www.omasco.com](http://www.omasco.com)  
[info@omasco.com](mailto:info@omasco.com)  
24665741



Consumer Protection Authority  
SOP-093-03 : ٢٠٢٥  
80079009 - 80077997 | خط المساعدة |