



RECALL DATE: 2ND JULY, 2024

MAZDA CX-60

BRAND OF COMMODITY	YEAR OF PRODUCTION	NUMBER OF AFFECTED COMMODITIES
MAZDA CX60 (2.5L)	2023	48



Due to inappropriate clutch control during deceleration, the clutch may be released with delayed timing, or engaged at unintended timing while decelerating. The engine speed may decrease during deceleration and in the worst case, result in engine stall at low speed. Once the vehicle power is switched OFF, the engine can be restarted.



Reprogram the Transmission Control Module (TCM) with modified software.

TO CHECK THE SERIAL NUMBERS OF THE AFFECTED COMMODITIES, PLEASE VISIT THE WEBSITE FOR RECALLS & WARNINGS: HTTP://RECALL.PACP.GOV.OM







24229100