



Recall

Recall Date: 26/08/2024

Porsche Taycan

Brand of Commodity	Year of Production	Number of Affected Commodities
Porsche Taycan	2020 – 2024	61 Cars

Recall Consequence

Brake hoses were installed on the left and right front axle of the affected vehicles which were designed with an insufficient bending radius.

Recall Action

The brake hose on the left and right of the front axle must therefore be replaced.

To check the Serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>



Service Department
Porsche Centre Oman
P.O. Box: 814, P.C:100
Tel. No. 2235 2940, ext: 400
Fax: 2235 2934
Email: porscheoman@satallc.co.om