



RECALL DATE: 28/08/2024

## **TOYOTA**

Brand of Commodity	Year of Production*	#Number of Affected Commodities
HILUX	January 16, 2023 through April 29, 2024	596

<sup>\*</sup>Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

Subject vehicles are equipped with a sport bar affixed through brackets. Under certain severe usage conditions, the brackets may crack causing the sport bar to potentially detach from the vehicle. If this occurs, it could become hazardous to other vehicles and pose a safety risk for pedestrian traffic.

**Recall Action** 

To remove the sport bar

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.go





