

Recall



BMW
MINI

Recall Date:4/9/2024

Brand of commodity	Year of Production	Number of affected commodities
BMW X5, X6, X7 and XM	2022-2024	344
BMW X2 & X1		73
BMW 7 Series		365
BMW 5 Series		207
Mini Countryman		30
Mini Cooper		4

Recall consequence

The recall is related to the possibility of signal interference in the brake assistance system, which may require higher brake operation force. In rare cases, not exceeding 3% to 4% of the vehicles, the warning system might be affected. However, the brake system will always remain operational, ensuring the required safety level according to German and European standards. The braking system continues to function regularly, maintaining effective safety levels under all conditions.

Recall Action

Accordingly, the focus will be on updating the potentially affected vehicles with the latest software version to ensure the detection of potential faults before they occur. In some cases, it may be necessary to replace the stability control unit if required. It should be noted that the potentially affected vehicles are as follows, including those sold, those not yet sold, and those in route to the company or in its possession.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>