

Recall



Recall Date: -04/09/2024.

Brand of Commodity	Year of Production	Number of Affected Commodities
103	2007 / 2013	Audi / A5-A4-Q5

Recall consequence

On Audi vehicles with TAKATA driver airbag manufactured within a specific period it is possible that the gas generator housing may be damaged if the driver airbag is deployed. This could cause small metal parts to become dislodged from the housing and potentially injure the driver or a passenger.

Recall Action

Replace Driver Airbag

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>