

## Commodity,s Picture

Recall Date: 29/12/2025



Hyundai Veloster FS

## Commodity,s Brand &amp;Model



Hyundai Santafe CM

## Brand of Commodity

## Year of Production

## Number of Affected Commodities

Hyundai Veloster

2011 - 2014

344

Hyundai Santafe

2011 - 2014

280

## Recall consequence

Electrical shorts in the HECU module may occur very rarely. It could increase the risk of an engine compartment fire.

## Recall Action

Replace the HECU fuse.



To verify the serial number of the goods Those affected please visit the recalls website And warnings by scanning the response code



Consumer Protection Authority  
80079009 - 80077997 خط المستهلك  
الرمز: SOP-093-03