



Recall Date: 22.10.2024

| Brand of Commodity | Year of Production | Number of Affected Commodities |
|-----------------------|--------------------|--------------------------------|
| AMG E 53 4M+ | 2019- 23 | 5 |
| AMG GT 43-53 4M+ | 2019- 23 | 6 |
| AMG CLS 53 4M and 4M+ | 2019- 23 | 5 |
| AMG CLS 53 4M+ Coupé | 2019- 23 | 1 |
| AMG E 53 4M+ Coupé | 2019- 23 | 2 |

Recall consequence: Mercedes-Benz AG has determined that on certain E-Class (213 platform), E-Class Coupe/Cabriolet (238 platform), CLS (257 platform) and AMG GT 4-door (290 platform) AMG vehicles with all-wheel-drive, the electrical connector of the transmission wiring harness might not have been reworked correctly. In this case, water might penetrate the connector and might create a short circuit over time. As a result, the short circuit might lead to thermal overload of the connector when the vehicle is parked.

Recall Action: As a precautionary measure Zawawi Trading Company team will replace the two-part wiring harness including the connector on the affected vehicles with a new one-part variant on the affected vehicles. The expected workshop visit for the replacement of the wiring harness will up to 3 hours. Zawawi Trading Company team will also contact the customers affected by the recall to arrange a convenient time from 22.10.2024 on all working days between 08:00AM-5:00 PM.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>