



2023-2024 Ram 1500 Pickup (DT)

Recall Date: 26 November 2024

Brand of Commodity	Year of Production	Number of Affected Commodities	
RAM 1500 Pickup (DT)	2023-2024	52	

Recall consequence

The Steering Column Control Module (SCCM) on about 10,570 of the above vehicles may have been built with mechanisms within the turn signal lever that experience an interference condition that disables the self-cancelling function. A turn signal which does not self-cancel and remains active after a completed tun may cause surrounding drivers to misunderstand the intent to change vehicle direction which can cause a vehicle crash without prior warning.

Reca**ll** Actior

Inspect and if necessary, replace the SCCM.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.gov.om





