Recall



TOYOTA & LEXUS

RECALL DATE: 11/12/2024

| Brand of Commodity | Year of Production* | #Number of Affected Commodities |
|--|--|------------------------------------|
| Toyota Crown | February 2, 2023 through August 4,2023 | 73 |
| Lexus ES350,LX500D,LX600,NX350, RX350,RX500H, UX200 | November 8,2022 through August 28,2023 | 967 |

^{*}Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

The subject vehicles are equipped with a front-view camera and a rear view camera used to capture and display an image of the area in front of and behind the vehicle. Due to insufficient laser welding of the camera case at the supplier during a specific production period, there is a possibility that the camera case may separate when exposed to external stress over time, allowing water to leak into the camera. If this occurs, the circuit inside the camera can short, leading to an inability to display an image of the area in front of and/or behind the vehicle.

Recall Action

To inspect and replace the camera if necessary

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.go





