



RECALL DATE: 9/12 / 2024

TOYOTA & LEXUS

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Toyota - Land cruiser	March 2,2021 through November 25,2022	3725
1 17/00		
Lexus - LX600	July 8, 2021 through November 25, 2022	901

^{*}Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

The subject vehicles are equipped with a specific V35A (3.5 L) engine that contains crankshaft main bearings which allow the crankshaft to rotate within the engine assembly while running. During a specific production period, there is a possibility that engine machining debris of a particular size and amount may not have been cleared from the engine during manufacturing and subsequently contaminated the engine assembly during the production process. For these engines in the subject vehicles, the pressure on the main bearings due to the engine configuration is such that, if the aforementioned machining debris adheres to the bearings and operation of the engine continues at higher loads over time, failure of the bearings may occur. This can lead to potential engine knocking, engine rough running, engine no start and/or an engine stall. In the subject vehicles, an engine stall while driving leads to a loss of motive power while driving at higher speeds can increase the risk of a crash.

Recall Action

To check & replace Engine assembly.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.go



Saud Bahwan Automotive LLC CR 1703412

Contact details: Toll free - 80073000, Mobile- 99851135

Working days: Sunday - Thursday Working Time: 8.00 - 17.00 hrs.



