

Recall



Recall Date: 2/1/2025

Accord-CRV-civic 2023-2024

Brand of Commodity	Year of Production	Number of Affected Commodities
Accord-CRV-civic	2023-2024	Total: 456 units

Recall consequence

Gasoline leak from the cracks on the solenoid component part of High-pressure pump and smell of gasoline fumes while driving and idling the vehicle. some cases large amount of leak visible. Cracks occurred in High pressure fuel pump solenoid component during supplier manufacturing process due to inappropriate machining and heat treatment.

Recall Action

The procedure will be carried out according to the technical instructions received from Honda.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>

