



## ISUZU TRUCK

RECALL DATE: 18.2.2025

Brand of Commodity	Year of Production	Number of Affected Commodities
ISUZU N-series	2024	42

## Recall consequence

Due to improper production of the injection pipe bracket, interference between an injection pipe and pipe clip may occur. If a vehicle is used in this condition continuously, fuel leaks may occur

## Recall Action

Replace the injection pipe bracket and pipe clip”

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>