

Recall



BMW

Recall Date: 20.02.2025

Brand of commodity	Number of affected commodities	Year of Production
BMW X3	2	2024
BMW 5 Series	3	
BMW 7 Series	21	
BMW X2	1	

Recall consequence

As a result of changes in the opening mechanism of the tailgate lock, it is possible that the tailgate might no longer lock completely after an opening procedure. In this case, the tailgate has a gap. Tightness is not ensured, and interior monitoring cannot be activated.

Recall Action

Renew the tailgate lock.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>

