



## RECALL CAMPAIGN FOR FUSO TRUCK

Recall Date: 06 March 2025

Brand of Commodity	Year of Production	Number of Affected Commodities
FUSO – FM & FK EURO 3	From 2021 to 2022	43

### Recall consequence

Due to the black substance (oxidation) formation on the contact surface of the combination switch, improper electrical conduction is caused.

### Recall Action

Replacement of the combination switch/turn lever.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>

