

**Recall Date : 25/02/2025**



Brand of Commodity	Year of Production	Number of Affected Commodities
Nissan Armada	2008 - 2011	3606
Nissan Pathfinder	2008 - 2011	3862
Nissan Xterra	2008 - 2011	1965

## Recall Cause

Due to an error in the supplier process, the driver's airbag emblem could detach from its mounting during the deployment of the airbag in the event of a road traffic accident. In such an event, the detached emblem may cause injury should it come into contact with an occupant.

## Recall Cause

To inspect the driver airbag module serial number and replace the cover.

To check the serial numbers of the affected commodities, please visit the website for recalls and warnings: <http://recall.pacp.gov.com>



خط المستهلك  
Consumer line  
80079009  
80077997



الحشار للسيارات  
Al Hashar Automotive

Call Us Toll-Free at  
**800 88088**