

Recall Date : 25/02/2025



Brand of Commodity	Year of Production	Number of Affected Commodities
INFINITI Q70	2011 - 2019	32

Recall Cause

On affected Q50 and Q70 vehicles, the supplier changed the ball yoke specification of the propeller shaft without reporting it to INFINITI. This part did not match the specifications outlined for mass production. As a result, there is a risk of non-conformity with durability specifications and a potential safety risk should the part break while driving.

Recall Cause

To replace the existing propeller shaft with a countermeasure propeller shaft.

To check the serial numbers of the affected commodities, please visit the website for recalls and warnings: <http://recall.pacp.gov.com>



خط المستهلك
Consumer line
80079009
80077997



الחסار للسيارات
Al Hashar Automotive

Call Us Toll-Free at
800 88088