



Recall Date: - 11/05/2025

Brand of Commodity	Year of Production	Number of Affected Commodities
Volkswagen - Teramont	2024	159

Recall consequence

An unsecured engine compartment cover could touch the hot area of the turbo charger and results in smoldering damage or even fire. The affected engine compartment cover has to be removed and will be replaced by new.

Recall Action

Removal of cover and Replacement new cover letter.



To check the serial number of the affected items, please visit the Recalls and Warnings website by scanning the QR code.



المنتمية للسيارات
Premium Motors

During Official Working Hours
Contact Number +96822845100



Consumer Protection Authority
80079009 • 80077997 خط المستهلك