



RANGE ROVER / RANGE ROVER SPORT 2024 - 2025

Recall Date: **8 May 2025**

Brand of Commodity	Year of Production	Number of Affected Commodities
RANGE ROVER / RANGE ROVER SPORT	2024 - 2025	24

Recall consequence

The middle seatbelt buckle in the second row of seats may have been incorrectly produced. An incorrectly positioned inner cable can lock the belt tongue and prevent correct locking. In the event of an accident, an improperly locked seatbelt buckle can increase the risk of injury.

Recall Action

Replacement of second row center seat belt buckle.



To check the serial number of the affected items, please visit the Recalls and Warnings website by scanning the QR code.



For more information
800 626 43
www.mhdacere.com



www.cpa.gov.om

Consumer Protection Authority
80079009 • 80077997 خط المستهلك