



2024 (JL) Jeep® Wrangler

Recall Date: **19 May 2025**

Brand of Commodity	Year of Production	Number of Affected Commodities
2024 (JL) Jeep® Wrangler	2024	23

Recall consequence

The rear fog lamps on about 996 of the above Built-Up Export (BUX) vehicles may have an intermittent electrical connection. The molding process for the fog lamp electrical connector created connector cavities which were too large, leading to a loose connection between the fog lamp and the electrical harness. Improperly functioning rear fog lamps may reduce the visibility of the vehicle to surrounding drivers in certain conditions.

Recall Action

Replace Rear Fog Lamp Socket and Bulb on Both Sides of the Vehicle.



To check the serial number of the affected items, please visit the Recalls and Warnings website by scanning the QR code.



For more information
800 22 008
www.mhdacere.com



www.cpa.gov.om

Consumer Protection Authority
80079009 - 80077997 خط المستهلك