Recall date:22/5/2025

Recall



	Number of Affected
Year of Production	Commodities
2024	389
	00,
	1
	Year of Production 2024



Due to tread thickness over spec at shoulder it cause of overheat during high speed specially Y speed category



Tyre replacement by other category or other brand



To verify the serial number of the goods Those affected please visit the recalls website And warnings by scanning the response code



Contact number 94335556/94292748



