

Commodity,s Picture

Recall Date: 29/12/2025

Commodity,s
Brand &Model

Hyundai Santafe MX5

Brand of Commodity	Year of Production	Number of Affected Commodities
Hyundai Santafe	2024	125

Recall
consequence

The main floor wire harness used in the subject vehicles could become damaged due to contact with the passenger -side, second -row bench seats folding hinge assembly. A damaged main floor wire harness could result in illumination of the air bag warning light, unintended air bag deployment, and / failing to deploy the air bags during a crash.

Recall Action

Dealers will notify owners to bring their vehicles to Hyundai Dealer to inspect and properly secure the wire harness. In the event wire harness damage is confirmed, the floor wire harness will be replaced with new one.

Dealers will inspect and, if necessary, remove and replace the finish on rear seat lower child seat LATCH anchorage bars.



To verify the serial number of the goods Those affected please visit the recalls website And warnings by scanning the response code



Consumer Protection Authority
80079009 - 80077997 خط المستهلك