

Recall



Honda Pilot

RECALL DATE: 28/08/2025

PILOT	Brand of Commodity	Year Of Production	Number of Affected Commodities
	Honda	2023	15
		2024	39
		2025	9

Recall consequence

The brake pedal pivot pin may not have been properly staked during assembly. Over time, the pivot pin can potentially back out of the brake pedal bracket causing side-to-side movement in the brake pedal. A loose brake pedal could lead to diminished or loss of braking function and/or the brake light to remain illuminated, potentially increasing the risk of a crash or injury.

Recall Action

The procedure will be carried out in accordance with the technical instructions provided by Honda.



To verify the serial number of the goods Those affected please visit the recalls website And warnings by scanning the response code



www.omasco.com
info@omasco.com
24665741



Consumer Protection Authority
80079009 - 80077997 خط المستهلك