



RECALL CAMPAIGN FOR FUSO TRUCK

Recall Date: 28 October 2025

Brand of Commodity	Year of Production	Number of Affected Commodities
TF Canter Light-duty trucks	2024	158

Recall consequence

Due to the insufficiency of the SSAM software, SSAM Clock Monitoring Unit (CMU) frequency, synchronization checks in the SSAM software are too sensitive, which leads to false triggers of error and SSAM reset. In the worst case, head lamps, tail lamps, turn lamps and wipers go off while driving.

Recall Action

Reprogramming new software SSAM by DTD tool.



To verify the serial number of the goods Those affected please visit the recalls website And warnings by scanning the response code



For more information, please call
24 500 500 or 24 500 502
from Sunday to Thursday between
08.00 am to 17.30 pm.



Consumer Protection Authority
خط المستهلك 80079009 - 80077997