



RECALL DATE: 05/11/2025

TOYOTA FORKLIFT

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Toyota Forklift 8FBE10-20	2016-2023	70

^{*}Not all vehicles in this production period, are affected.

Recall consequence

The subject vehicles are certain electric Forklifts. There is a possibility that it may cause the welded part of the overhead guard to get cracked. Moreover, in case of continuing to use the forklift vehicle with the cracked welded part of the overhead guard, there is a possibility that it may cause the welded part to get fractured and the component of the overhead guard to fall off.

Recall Action

To replace the overhead guard roof bar







[#]Subject to revision, based on the information received from the manufacturer, from time to time.