



Recall

HINO 700 SERIES

RECALL DATE: 05-02-2026

Brand of Commodity	Year of Production*	#Number of Affected Commodities
ZS1EPVA-VRP	2024 to 2025	140

*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

In some vehicles of Hino 700 Series, strength of supply pump housing is insufficient due to inappropriate surface treatment process. Therefore cracks may develop when repeated to the supply pump, resulting in fuel leak.

Recall Action

Defect in the durability of the supply cover, which is considered insufficient due to an improper surface treatment process that causes cracks when repeating the process, which leads to fuel leakage.



To check the serial number of the affected items, please visit the Recalls and Warnings website by scanning the QR code.



Contact details: Toll free - 80073000
Working days: Sunday - Thursday
Working Time: 8:00 - 17:00 hrs.



Consumer Protection Authority
80079009 - 80077997