



Recall

Recall Date: 21/11/2023

Brand of Commodity

Year of Production

Number of Affected
Commodities

AMG SL 55 4MATIC+

2022-2024

7

Recall consequence

on certain SL (232 platform) vehicles with M177 engine the routing of the 12V-starter/generator wiring harness might not meet specifications. In this case, the wiring harness could chafe on the drive shaft. As a consequence, a short circuit, which could potentially result in a loss of propulsion, cannot be ruled out. Additionally, due to the high electrical currents potentially flowing through this connection, the temperature in this area might increase. Legal requirements might not be met.

Recall Action

As a precautionary measure Zawawi Trading Company team will check the routing of the wiring harness on the affected vehicles and rework it. The expected workshop visit for the check and rework of the wiring harness will take around 30 minutes. Zawawi Trading Company team will contact the customers affected by the recall to arrange a convenient time from 21/11/2023 on all working days between 08:30AM-5:00 PM to check and rework of the wiring harness and rework, if necessary.

To check the serial numbers of the affected commodities, please visit the website from Recalls & Warning: <http://recall.pacp.gov.om>

