



Recall

KIA

Mohave (HM)

RECALL DATE: 12-02-2024

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Mohave (HM)	November 2007 ~ May 2013	249

*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

On some Mohave (HM) of 2007-2013 MY produced within specific production date range provided in TSB, Insufficient adhesive may have been applied to secure the headliner plates to the headliner. As a result, under certain circumstances, the headliner plate(s) may detach from the headliner upon deployment of the side curtain airbags. An occupant may be injured due to potentially insufficient adhesive applied to the headliner plate(s). Estimated percentage of defect is 1% (defect ratio). However, Kia is conducting this recall as a preventive measure to avoid the risk during the deployment of side curtain airbags.

Recall Action

Verify affected Mohave (HM) vehicles as per the VIN list, inspect the headliner plates to the headliner and secure the headliner using adhesive as recommended by KIA. All affected vehicles will be inspected and repaired at no expense to the vehicle owner.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacfp.gov.om>



Contact details: Toll free - 80073222
Working days: Sunday - Thursday
Working Time: 8:30 - 17:30 hrs.



السلطنة
مجلس حماية المستهلك
Consumer Protection Authority
www.pacfp.gov.om



السلطنة
خط المستهلك
80079009
80077997