



Recall

TOYOTA

YARIS & VELOZ

RECALL DATE: 31/01/2024

Brand of Commodity	Year of Production*	#Number of Affected Commodities
YARIS	June 9,2022 through September 6,2023	1260
VELOZ	October 19,2021 through October 3,2023	119

*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

For vehicles supplied by Daihatsu or developed mainly by Daihatsu and manufactured by Toyota (TMM1N, TMT, TMV), due to improper tightening instruction for the nut(s) fixing the upper portion(s) of the front shock absorber(s), the tightening torque of the nut(s) might be insufficient. If the vehicle is operated continuously in this condition, the nut(s) may become loose, causing abnormal noise, and in the worst case, the nut(s) may come off, resulting in loss of vehicle stability.

Recall Action

To retighten the front shock absorber nuts.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.go>



Contact details: Toll free - 80073000
Working days: Sunday - Thursday
Working Time: 8:00 - 17:00 hrs.



الهيئة العامة لحماية المستهلك
Consumer Protection Authority
www.pacp.gov.om



خط المستهلك
Consumer line
80079009
80077997