

# Recall



## 2014-2016 Jeep Cherokee

Recall Date: **30 April 2024**

Brand of Commodity	Year of Production	Number of Affected Commodities
(KL) Jeep Cherokee	2014-2016	104

### Recall consequence

The Power Liftgate Module (PLGM) on about 104 of the above vehicles are failing due to an electrical short after FCA US LLC ("FCA US") Recall ID R27(NHTSA Recall ID 15V-393) or FCA US Recall ID R67 (NHTSA Recall ID 15V-826) remedial actions are performed. An electrical short in the power lift gate module may lead to a vehicle fire with the ignition on or off. A vehicle fire can result in increased risk of occupant injury and/or injury to persons outside the vehicle, as well as property damage.

### Recall Action

The power liftgate module must be inspected for evidence of water intrusion and electrical connector corrosion. On vehicles found with corrosion in the power liftgate module electrical connectors, the module and electrical connectors will be replaced.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>



خط المستهلك  
Consumer line  
80079009  
80077997



هيئة حماية المستهلك  
Consumer Protection Authority  
[www.pacp.gov.om](http://www.pacp.gov.om)



For more  
information **800 22 008** | [www.nhtsa.gov](http://www.nhtsa.gov)