



Recall

RECALL DATE: 15/05/2024

TOYOTA RAIZE

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Raize	September 12,2022 through January 13,2023	65

*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

Due to the assemble fault at the brake caliper assembly line, the assembly tools interfered with the slide pin boots during assembly, it caused damage on the boots. If the water enters in the slide pin boots and cause the rust, it may lead to early wear of the brake pads.

Recall Action

To replace the front disc brake cylinder slide pin boot and if necessary, replace the brake cylinder mounting.

This Customer Satisfaction Campaign is set to expire on 31/01/2027

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov>



Saud Bahwan Automotive LLC
CR 1703412
Contact details: Toll free - 80073000
Working days: Sunday - Thursday
Working Time: 8.00 - 5.00 hrs.



خط المستهلك
Consumer line
80079009
80077997