



RECALL

RECALL DATE: 27TH JUNE, 2024

MAZDA CX-60

BRAND OF COMMODITY	YEAR OF PRODUCTION	NUMBER OF AFFECTED COMMODITIES
MAZDA CX60 (2.5L)	2023	55

RECALL
CONSEQUENCE

While idling or driving at low speed after the engine is restarted under the condition that the fuel temperature in the fuel tank is exceeding 55°C (evaporative gas concentration is increasing), the engine stall may occur. The engine can be restarted using the push button start.

RECALL ACTION

Reprogram the Powertrain Control Module (PCM) with modified software.

TO CHECK THE SERIAL NUMBERS OF THE AFFECTED COMMODITIES, PLEASE VISIT THE WEBSITE FOR RECALLS & WARNINGS: [HTTP://RECALL.PACP.GOV.OM](http://RECALL.PACP.GOV.OM)



24229100