

Recall



Recall Date: - 30/09/2024.

Brand of Commodity	Year of Production	Number of Affected Commodities
19	2024	Audi e-Tron GT

### Recall consequence

On Audi e-Tron GT vehicles manufactured within a specific period, cracks may occur on the brake hoses on the front axle over time, resulting in brake fluid escaping. Consequently, we cannot rule out the sudden failure of the brake circuit on the front axle, brake circuit on the rear axle remains functional. However, your vehicle's braking performance will be noticeably restricted.

### Recall Action

The brake hoses and brackets on the front axle must be replaced on the affected vehicles.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>



خط المستهلك  
Consumer line  
80079009  
80077997

During Official Working Hours  
Contact Number +96822845100



التميزة للسيارات  
Premium Motors