



ZRV-CRV-civic

Recall Date: 11/2/2025

Brand of Commodity	Year of Production	Number of Affected Commodities
ZRV-CRV-civic	2023-2024-2025	Total: 459 units

Recall consequence

Due to decrease of the grease amount in the worm wheel gear meshing area of the EPS gear box during use, the sliding resistance at the meshing area increases and the torque fluctuation when turning the steering becomes larger, resulting in an abnormal noise or sticking occurs when turning the steering.

Recall Action

The procedure will be carried out according to the technical instructions received from Honda.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.gov.om





