

**Recall Date : 25/02/2025**



Brand of Commodity	Year of Production	Number of Affected Commodities
INFINITI QX60	2022 - 2023	41

#### Recall Cause

During the production of the owner's manual, the service interval of the oil change was not correctly displayed. This was due to missed feedback between the supplier and INFINITI and may mislead the customer while performing periodic services.

#### Recall Cause

An addendum card (Owner's manual supplement) will be added to the owner's manual in order to inform the customer of the correct oil service interval.

To check the serial numbers of the affected commodities, please visit the website for recalls and warnings: <http://recall.pacp.gov.com>



خط المستهلك  
Consumer line  
80079009  
80077997



الحشار للسيارات  
Al Hashar Automotive

Call Us Toll-Free at  
**800 88088**