



Recall

TOYOTA & LEXUS

LAND CRUISER 300 & LX700h

RECALL DATE: 17/02/2026

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Toyota Land Cruiser300 Lexus LX700h	2024-2025	90

*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

The subject vehicles are equipped with a specific engine ECU. Due to improper programming of learning conditions for fuel injection, the ECU may incorrectly detect abnormal fuel pressure even when it is normal during engine warm-up. This will lead to the engine warning light illuminating and the vehicle entering a failsafe driving mode in which the vehicle can still be driven with limited motive power and vehicle speed approximately 60km/h.

Recall Action

To reprogram the engine ECU.

Note: This Campaign is set to expire on September 30, 2028



To check the serial number of the affected items, please visit the Recalls and Warnings website by scanning the QR code.



Contact details: Toll free - 80073000
Working days: Sunday - Thursday
Working Time: 8:00 - 17:00 hrs.



www.cpa.gov.om

Consumer Protection Authority
80079009 - 80077997 خط المستهلك

التاريخ : فبراير 2025

الاصدار : 04

الرمز: SOP-093-03