



RECALL

RECALL DATE: 5TH MARCH, 2024

MAZDA CX-60 & MAZDA CX-90

BRAND OF COMMODITY	YEAR OF PRODUCTION	NUMBER OF AFFECTED COMMODITIES
MAZDA	2023	90

RECALL CONSEQUENCES

While driving, the customer may feel a sudden increase of effort when steering the vehicle. Sudden and unexpected change of steering effort while driving may increase the risk of a crash.

RECALL ACTION

1. Reapply grease to the steering gear teeth.
2. Replace the spring engaging the worm gear with an improved part. The improved spring will reduce the spring force to the worm gear in the steering assembly.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>