



Recall

TOYOTA & LEXUS LC300 & LX600

RECALL DATE: 8/04/2024

Brand of Commodity	Year of Production*	#Number of Affected Commodities
Land cruiser 300	January 11,2021 through June22,2023	5937
Lexus LX600	August 17,2021 through June 22,2023	1571

*Not all vehicles in this production period, are affected.

#Subject to revision, based on the information received from the manufacturer, from time to time.

Recall consequence

In the subject vehicles, there is a possibility that the knocking control in Engine Control Computer may not work properly when low octane rate gasoline is used due to inappropriate program. If this the vehicle is driven continuously under this condition, a spark plug and/or other component part in combustion chamber may be melted, resulting in abnormal vibration and/or illuminates malfunction indicator lamp (MIL) due to engine misfire.

Recall Action

To reprogram the Engine Control Computer.

This Customer Satisfaction Campaign is set to expire on 28/2/2027.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.go>



Saud Bahwan Automotive LLC
CR 1703412
Contact details: Toll free - 80073000
Working days: Sunday - Thursday
Working Time: 8.00 - 17.00 hrs.



خط المستهلك
Consumer line
80079009
80077997