
AUDI-e Tron - GT





Recall Date: - 10/06/2024.

Brand of Commodity	Year of Production	Number of Affected Commodities
11	2023	Audi e-Tron GT

Recall consequence

The battery modules of the vehicle's high-voltage battery must be checked during a workshop visit for safety reasons. The scope of the work involved will require the vehicle to be in the workshop for between one and two days. If it is necessary to replace some of the battery modules, this may take up to

three days.

Recall Action

The high-voltage battery must be checked on the affected vehicles and, if necessary, one or more modules must be replaced

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: http://recall.pacp.gov.om





