



Chevrolet Groove

Recall Date: 15/02/2024

Brand of Commodity	Year of Production	Number of Affected Commodities
Chevrolet Groove	2023	4

Recall consequence

The certification label located on the driver's side B-pillar contains incorrect Gross Vehicle Weight (GVW) as 1260 Kg instead of 1670 Kg.

Recall Action

Dealers will replace the vehicle certification label on the driver's side B-pillar.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>



OMAN TRADING ESTABLISHMENT LLC

Contact details OTE - Toll free number 80050002 on all working days, 08:00AM to 01:00PM and 2:00PM to 05:00PM