

Recall



2022-2023 Jeep Grand Cherokee 2021-2023 Jeep Grand Cherokee L

Recall Date: **21 April 2024**

Brand of Commodity	Year of Production	Number of Affected Commodities
Jeep Grand Cherokee	2022-2023	170
Jeep Grand Cherokee L	2021-2023	

Recall consequence

The Upper Control Arm (UCA) pinch bolt on about 170 of the above vehicles may have been damaged during vehicle assembly. A damaged pinch bolt may break and result in the loss of clamp load between the UCA ball joint and the knuckle. A loss of clamp load may result in the UCA separating from the knuckle and the wheel falling outboard, which can cause a vehicle crash without warning.

Recall Action

Replace the front UCA to steering knuckle pinch bolt on both sides of the vehicle by following the directions outlined in the Service Procedure.

To check the serial Numbers of the affected commodities, please visit the website for Recalls & Warnings: <http://recall.pacp.gov.om>



خط المستهلك
Consumer line
80079009
80077997

هيئة حماية المستهلك
Consumer Protection Authority
www.pacp.gov.om



For more
information **800 22 008** | www.mhdacere.com

C.P.No. 1429946